

# FIELD INSPECTION REPORT

Date of Inspection :	05.12.20	District:	Sarmastipur
Division :	PATARI	Length (km):	0.330 Km
Name of the Road:	PWD Path to Mohiuddinagar to Thana Road PWD Path tak		
Scheme/Programme:	MAINTENANCE		
Package No.:	N/A	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Ongoing</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>MR</u>		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started. only information Board installed.

Pramod  
05.12.20  
(Signature)

NAME: Pramod Kumar Ray  
DESIGNATION: J.E

### FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020		District: Sonapatpur
Division : PATORI		Length (km): 0.800 Km
Name of the Road: Kursaha to Dharanpur Durg Mandir Bandh Sadak		
Scheme/Programme: MAINTENANCE		
Package No.:	N/A	Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ongoing
Work is a case of:		New Connectivity/Up gradation/ Maintenance MR

  

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Work is not started, only information Board installed.

Pranod  
5.12.20  
(Signature)

NAME: Pranod Kumar Ray

DESIGNATION: J.E.