


## FIELD INSPECTION REPORT

|                                                         |                                              |
|---------------------------------------------------------|----------------------------------------------|
| <b>Date of Inspection :</b> 05-12-2020                  | <b>District:</b> WEST CHAMPARAN              |
| <b>Division :</b> BACHHA-1                              | <b>Length (km):</b>                          |
| <b>Name of the Road:</b> - PARSAUNI FARM TO BISHANPURWA |                                              |
| <b>Scheme/Programme:</b>                                | MAINTENANCE - old (3054) out of maintenance. |
| <b>Package No.:</b>                                     | <b>Road Id No.:</b>                          |
| <b>Status of the Project:</b>                           | Ongoing/Completed/Under Maintenance          |
| <b>Work is a case of:</b>                               | New Connectivity/Up gradation/ Maintenance   |

| Sl. No.   | Parameters to be checked                                                                                             | Remarks   |
|-----------|----------------------------------------------------------------------------------------------------------------------|-----------|
| <b>1.</b> | <b>Pavement</b>                                                                                                      |           |
| a)        | Road Junction condition                                                                                              | S/U ✓     |
| b)        | Condition of Surfacing                                                                                               | S/U ✓     |
| c)        | Riding Quality                                                                                                       | S/U ✓     |
| d)        | Road Camber                                                                                                          | S/U ✓     |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓  |
| f)        | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓  |
| g)        | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓  |
| <b>2.</b> | <b>Cross Drainage</b>                                                                                                |           |
| a)        | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U ✓ |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U   |
| c)        | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| <b>3.</b> | <b>Road Furniture</b>                                                                                                |           |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| <b>4.</b> | <b>Compliance History</b>                                                                                            |           |
| a)        | Status of ATR's & any others                                                                                         | No        |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | ✓ |

  
 05/12/2020  
 (Signature)

NAME: Md. Shahansha Alam

DESIGNATION: J.E