

# FIELD INSPECTION REPORT

|                        |                                            |              |             |
|------------------------|--------------------------------------------|--------------|-------------|
| Date of Inspection:    | 05/12/2020                                 | District:    | Banke       |
| Division:              | Banke                                      | Length (km): | 3.82 K.M.   |
| Name of the Road:      | Jamsil - LOYN Road to Haripur              |              |             |
| Scheme/Programme:      | MAINTENANCE                                |              |             |
| Package No.:           | RM/BA/BAN/20/0008                          | Road Id No.: | 20703502099 |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |             |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |             |

| Sl. No. | Parameters to be checked                                                                                             | Remarks         |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------------|
| 1       | <b>Pavement</b>                                                                                                      |                 |
| a)      | Road Junction condition                                                                                              | S/U Ongoing     |
| b)      | Condition of Surfacing                                                                                               | S/U Ongoing     |
| c)      | Riding Quality                                                                                                       | S/U Ongoing     |
| d)      | Road Camber                                                                                                          | S/U Ongoing     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No N.A      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No N.A      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Ongoing  |
| 2       | <b>Gross Drainage</b>                                                                                                |                 |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U Ongoing |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U Ongoing |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N.A     |
| 3       | <b>Road Furniture</b>                                                                                                |                 |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No Ongoing  |
| 4       | <b>Compliance History</b>                                                                                            |                 |
| a)      | Status of ATR's & any others                                                                                         |                 |

Overall Rating :

|                                             |                  |
|---------------------------------------------|------------------|
| Satisfactory (S)                            | Satisfactory (S) |
| Satisfactory but requires Improvement (SRI) |                  |
| Unsatisfactory (U)                          |                  |

*Prin*  
05/12/2020  
(Signature)

NAME: Ashok Kumar Siblea

DESIGNATION: Junior Engineer