FIELD INSPECTION REPORT

	nspection:		District: Lakhisamai		
livision: Lakhisares		3283	Length (km): 1.23 km		
ame of	the Road:	mb(W/s) of Genu	a Pursando Rato Ka	nag Rd	
cueme/	rogramme:	MAINTENANCE			
ackage			Road Id No.: 2080390	005	
	the Project:	Ongoing/Completed/			
86 TT 7717	a case of:	New Connectivity/U	p gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No				
f)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
. 2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No	
44	Compliance History				
a)	Status of AT	Status of ATR's & any others			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Road is in Technical Bid.

NAME: Anisur Rochrongro

DESIGNATION: Executive Engineer

(Signature) कार्यपालक अभियन्ता गामीण कार्य विभाग कार्य प्रमह्त् लाखीसराय