## FIELD INSPECTION REPORT

		TIDES	the state of the s	
e of Inspect	tion .		District: Laxuscaron	the same of the sa
			Length (km): 2.87 km	NAME OF THE OWNER, WHEN PERSON AND PARTY OF THE OWNER, WHEN PERSON
	oad: T	icz - Tes to	Barabfire	
heme/Progr		MAINTENANCE	20020	98
ckage No.:			Road Id No.: 208039020	16
atus of the I	Project:	Ongoing/Completed	/Under Maintenance	The state of the s
ork is a cas	e of:		Jp gradation/ Maintenance	Remarks
Sl. No. Parameters to		Parameters to	be checked	Kema
1. Pay	vement	The second second	ner Carrier (1902) Karilla	A CONTRACTOR OF THE PARTY OF TH
Steel Light Co.	ad Junction	condition		S/U
				S/U
b) Co	Condition of Surfacing			S/U
c) Ri	Riding Quality			S/U
d) Re	Road Camber			
e) W	hether fre	e from defects su	ich as visible cracks, exposed	Yes/No
aggregates in case		a case of CC Pavemer		Yes/No
	f) Contraction Joints provided or not			Yes/No
g) (	Compaction	of flank/slope & rain	cuts if any	165/110
The Control of the Control of the Control	Cross Drainage			2330 10 . 65
a) (	Condition o	of head walls in Hume	pipe culverts including its painting	S/SRI/U
1			walls, Slab in RCC culverts	S/SRI/U
1 - 1	Condition of railings/slab/approach			S/SRI/U
3.	Road Furniture			Daker Hall
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained			Yes/No
4	Complian	ice History		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Road is in Technical Bid.

NAME: Asisur Rahonom

DESIGNATION: Executive Engineer

Status of ATR's & any others

(Signatura अभियन्ता ग्रामीण कार्य विभाग कार्य ज्याहरू