

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District:	Sheikhpura
Division :	Sheikhpura	Length (km):	2.13 KM
Name of the Road:	Aighe High school to Katarina Katar Harigan Tola		
Scheme/Programme:	MAINTENANCE (Ongoing)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	-SAU-NA →
b)	Condition of Surfacing	-SAU-NA →
c)	Riding Quality	-SAU-NA →
d)	Road Camber	-SAU-NA →
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No-NA →
f)	Contraction Joints provided or not (CC Pavement)	Yes/No-NA →
g)	Compaction of flank/slope & raincuts if any	Yes/No-NA →
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-NA →
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U-NA →
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U-NA →
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

yet to be done

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

S/A
05/12/2020
(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A.E.