

FIELD INSPECTION REPORT

Date of Inspection:	06/12/2020	District:	Sheikhpura
Division:	Sheikhpura	Length (km):	2.440 KM
Name of the Road:	Repair of Road from Sheikhpura Lakhisari Road to Mahsar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA →
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA →
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA →
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Sign board, Km & 200m stones not maintained properly

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

SMB
06/12/2020
(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A.E.