FIELD INSPECTION REPORT

	the Road: (const. From J	Tamuni Pul Tal Sharpe	2 7701351
	rogramme:	MAINTENANCE	in the second se	The second secon
ckage I		To	Road Id No.: 208040010	5 O Ys
			going/Completed/Under Maintenance w Connectivity/Up gradation/ Maintenance	
Sl. No.		**************************************	Parameters to be checked	
1	Pavement	Payamant		
a)	MELLINGS OF SALES	Road Junction condition S/U		
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any Yes			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
4.	Compliance History			
a)	Status of ATR's & any others			
Overa	all Rating	:		
Satisfactory (S) Satisfactory but requires Improvement (SRI)				
		Unsatisfactor		

This Road is in CS Process.

NAME: Arisar Rahman

DESIGNATION: Executive Engineer

