FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020		District: Jane			
Division: Janui		Length (km): 2.50 KH			
Name of the Roa	id: Janua Lice 1		pyr Roas		
Scheme/Progran	me: MAINTENANO	DE .			
Package No.:	MR-N / 19-20/James		11		
Status of the Pro Work is a case of	1	Ongoing/Completed/Under Maintenance			
NAME OF TAXABLE PARTY.		ty/Up gradation/ Maintenance			
Sl. No.	Parameter	s to be checked	Remarks		
1. Paveme	ent				
a) Road Ju	Road Junction condition				
b) Condition	Condition of Surfacing				
c) Riding	Riding Quality				
d) Road C	Road Camber				
e) Whethe aggrega	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f) Contrac	Contraction Joints provided or not (CC Pavement)				
g) Compac	Compaction of flank/slope & raincuts if any				
2. Cross D	Cross Drainage				
a) Condition	Condition of head walls in Hume pipe culverts including its painting				
b) Condition	Condition of Abutment & Wing walls, Slab in RCC culverts				
	Condition of railings/slab/approach for Bridges				
3. Road Fi	urniture		100 E		
stones/Pa	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4. Complia	ince History	Total to	and the state of		
a) Status of	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	161
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Out to of 12/2020 (Signature)

N			-
re.	•	RA.	