FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020			District: Janw	
Length (km): 5.511 lc H				
Name of	the Road: Jan	Mui-LKR PWID 1	Road to Nim Namado Harn	ahq-Bhatgha
Scheme/I	Programme:	MAINTENANCE		
Package	No .: MR-MI	19-20/Janui/13	Road Id No.: 208041010	121
Status of	the Project:	Ongoing/Completed	/Under Maintenance	
Work is	a case of:	New Connectivity/	Jp gradation/ Maintenance	
SI-No.			re checked	Remarks
i	Pavement .		Control of the second of the s	
a)	Road Junction condition			S/U N/A
b)	Condition of Surfacing			S/U W/A
c)	Riding Quality			S/U N/A
d)	Road Camber			SAU NI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			¥es/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No-
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Farniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
WE SEE	reomotitue etitios/2 - 22 - 22 - 23 - 24 - 24 - 24 - 25 - 25 - 25 - 25 - 25			
a)				K/A
	L		S	nguing!
Overall Rating :		Satisfactory (S)		
		Satisfactory bu	t requires Improvement (SRI)	
		Unsatisfactory	(U)	

Just te 06/12/2020 5.E (Say pracked h Crupts) (Signature)

NAME:

DESIGNATION: