FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020			District: Janu'		
Division:			Length (km): 3.50 KM		
Name of	the Road: Jos	jui Lakhisaza	i PWD Road to Mistroigh	no Road	
scheme/	rrogramme:	MAINTENANCE	V		
Package		119-20/59HW11	Road Id No.: 208041010	155	
Status of	the Project:		d/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance				Control of the Contro	
Sl. No.		Parameters to	be checked	Remarks	
	Payement	u salah sa			
a)	Road Junction	√S/U			
b)	Condition of S	SAU			
c)	Riding Quality	SAU			
d)	Road Camber	SAU			
e)	Whether free aggregates in c	Yes/No A			
f)	Contraction Jo	Yes/No /			
g)	Compaction of	Yes/No			
2.	Cross-Diainage				
a)	Condition of h	S/ SRI/U -			
b)	Condition of A	S/SRI/U			
c)	Condition of ra	S/SRI/U			
3.	Road Furnitu				
a)	Whether sign stones/Paveme	Yes/No			
4.	Compliance I	listory			
a)	Status of ATR	NIA			

Overall Rating

Satisfactory (S)	'5'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Jub to
06/12/2020
5.E
(Jay Bukush burto)
(Signature)

-			-	-
N	Λ	n	78	ю.
N	п	ш,		