

FIELD INSPECTION REPORT

Date of Inspection :	6/12/2020	District:	Jamui
Division :	Jamui	Length (km):	3.223
Name of the Road:	1029 - Jamui - Kanyakol Purb road to Kaldaiya - Rishnupur Road (VR29)		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Jamui/15	Road Id No.:	20804102096
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Dnegging

NAME:

DESIGNATION:

fy
6/12/20
A.C

6/12/20
A.C

(Signature)