


FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 4.93 km	
Name of Road :- A.J.B. to Bhikampurhat via Sakur			
Scheme/Programme :- M.R. - old.		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :-		Ongoing/Complete/Under Maintenance ☒	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition	☒ S/U	
b)	Condition of Surface	☒ S/U	
c)	Riding Quality	☒ S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒	
f)	Construction Joints provided or not (CC Pavement)	☒ Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	☒ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 3.12.20
 J.E. Patel