

FIELD INSPECTION REPORT

DATE OF INSPECTION:	05-12-2020	DISTRICT:	PURNIA
DIVISION:	DHAMDARA	LENGTH:	1.650 K.M
NAME OF THE ROAD:	DAKAITA P.M. Road To RUPALI Purnea Pakki Road via Sadeli		
SCHEME/PROGRAMME:	MAINTENANCE		
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	—	
B	CONDITION OF SURFACING	—	
C	RIDING QUALITY	—	
D	ROAD CAMBER	—	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	—	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	—	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	—	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	—	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	—	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	—	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	S	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	—	
OVERALL RATING			
	SATISFACTORY(S)	S	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	—	
	UNSATISFACTORY(U)	—	

NAME: - PRAMOD KUMAR
DESIGNATION: JUNIOR-ENGR.

Prumod
05-12-2020
SIGNATURE