FIELD INSPECTION REPORT		
DATE OF INSPECTION:	05-12-2026 DISTRICT: PURNEA	
DIVISION:	DHAMDATIA LENGTH: 0.701cm	
NAME OF THE ROAD:	DHAMDAHA PURNTA SH SE DHAMDAHA PWO PATHTAI	
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	3
В	CONDITION FO SURFACING	
C	RIDING QUALITY	
D	ROAD CAMBER	ے
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	yes
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	M· #
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	7-5
2	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	M.A
A	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	M. A
С	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	M- 4
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	Yes
4	COMPLIANCE HISTORY	
A	STATUS OF ATR"S & ANY OTHERS	HO AMY ATR.
OVERALL RATING		
OVERALE NATIO	SATISFACTORY(S)	151
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	LINE ATISE ACTORY(U)	

NAME: - PRAMODICUMAR DESIGNATION: DUNIDR-EHGG