	FIELD INSPECTION REPORT	
DATE OF INSPECTION:		NEX
DIVISION:		
NAME OF THE ROAD:	PURNEA RUPAULI SHISE PW	D PATH TAL
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	3
В	CONDITION FO SURFACING	. u,
С	RIDING QUALITY	
D	ROAD CAMBER	. —
Ε	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	He A.
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N. 4
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	Yes
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	_
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	_
c	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	_
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	Yes
4	COMPLIANCE HISTORY	
A	STATUS OF ATR"s & ANY OTHERS	DO AND ALK
VERALL RATING		
TEINER INTING	SATISFACTORY(S)	-
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)	٠٠,

SIGNATURE

PRAMOD KUMAR DESIGNATION: JUNTOR. EHLY.