


FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020		District: Kathham.
Name of Road:		Dighoch (Hamsua) To Matna Nagar.
Scheme/ Programme:	MAINTENANCE New Mainm Policy	
Package No.	Road ID No.	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	N/A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	N/A
c)	Condition of railings/slabs/approach for Bridges	N/A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	N/A
4	Compliance History	
a)	Status of ATR & any others	N/A

Overall Grading:

Satisfactory (S)	In Tender process
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Satish chaudhary
 Designation Assistant engineer
 RUD Mainhori


 (Signature) 06/12/2020