

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020		District: Katihar	
Name of Road:		M/R of Road from house of Manoj sah village Kabilpur to Mahananda Bandh panchayat south Lalgaon in prantpur Block-	
Scheme/ Programme:		MAINTENANCE (FDR MR 2245)	
Package No.		Road ID No. 21105408001	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		S
b)	Condition of Surfacing		S
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		S
f)	Contraction Joints provided or not (CC Pavement)		S
g)	Compaction of flank/slope & raincuts if any		S
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting		N.A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		N.A
c)	Condition of railings/slabs/approach for Bridges		N.A
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.		S
4	Compliance History		
a)	Status of ATR & any others		N.A

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: SATISH CHAUDHARY
 Designation: AG, Prantpur
 RWD, Manihari

Sany 06/12/2020
 (Signature)

Note :- यह पथ रीशना PWD से कबीलपुर तक (लम्बाई - 2.4 Km) के नाम से वर्ष 2018-19 में FDR NR के अन्तर्गत बने हुए हैं जो मुरझाने लगे हैं।