

FIELD INSPECTION REPORT

Date of Inspection: 06.12.2020		District: Katoham.
Name of Road:		Repair of Road Gyanda H. School Roshna road from house of manoj sah Samudalle Chawan village Kabilpur, Rodanga vill. NH-81 of west part. (Panchayat South Lalgarh in prantpur Block)
Scheme/ Programme:	MAINTENANCE (FDR MR 2245)	
Package No.	Road ID No. 21105408002	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	N.A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	NA
c)	Condition of railings/slabs/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	S
4	Compliance History	
a)	Status of ATR & any others	NA

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: SATISH CHAUDHARY
Designation AR, Prantpur
RWD, Manikari

Satish 06/12/2020
(Signature)

Note: - यह यह Roshna RWD से कबिलपुर नर (मार्ग - 2.4 km) के नाम से वर्ष 2018-19 के FDR MR के अनुसार कार्य पूर्ण हो जो अग्रिम अवधि में हो