

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020		District: Katohar
Name of Road:		Barri Bathna to chitauria.
Scheme/ Programme:	MAINTENANCE	
Package No.	Road ID No. 21105708013	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	N/A
a)	Road Junction Condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	
c)	Condition of railings/slabs/approach for Bridges	
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	
4	Compliance History	
a)	Status of ATR & any others	

Overall Grading:

Satisfactory (S)	PMGSY
Satisfactory but requires Improvement (SRI)	Re tender
Unsatisfactory (U)	

Name:

SATISH CHAUDHARY

Designation

AE, Prampur
RWD, Manikari

Satish 06/12/2020
(Signature)

Note: → यह यह PMGSY-II योजना के अंतर्गत Re tender में है।