

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020		District: Katihar.
Name of Road:		PWD path to Malikipur Huma Hazra BR 16/10 (NBA) P-III/IV
Scheme/ Programme:	MAINTENANCE	
Package No.	Road ID No. 21105708014	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	N/A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	N/A
c)	Condition of railings/slabs/approach for Bridges	N/A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	S
4	Compliance History	
a)	Status of ATR & any others	N/A

Overall Grading:

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

SATISH CHAUDHARY

Designation

AG, Prayagrah
PWD, Mainwari

Satish/06/12/2020
(Signature)

Note: → यह पथ PWD Road to Mallickpur (Prayagrah) (Length = 10.5 km) के नाम से वर्ष 2018-19 में FDR MR के अन्तर्गत कार्य हो चुका है जो अनुसंधान अन्तर्गत में है।