FIELD INSPECTION REPORT

Package	Programme:	Baribathna to Chitamia-11 BR 1605 (RWD)	
		MAINTENANCE (MR - OLD)	
Status of	No.	Road ID No. 21105408021	
	the Project:	Onging/Completed/Under Maintenance	
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	The state of the s	Parameters to be Checked	Remark
1.1	Pavement		y projekty ka
a)	Road Junction Co	ndition	7
b)	Condition of Surfa	cing	
c)	Riding Quality	,	
d)	Road Camber		
	Whether free from CC Pavement	defects such as visible cracks, exposed aggregates in case of) .
f)	Contraction Joints	s provided or not (CC Pavement)	(N/
g)	Compaction of flar	nk/slpoe & raincuts if any	177
2	Cross Drainage		
a)	Condition of heady	walls inn Humepipe culverts including its painting	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		
c)	Condition of railing	gs/slabs//approach for Bridges	
3	Road Furniture		
		ds/informatory/cautionary Board/Km & 200m stone/ arkings are provided and maintained.	
4	Compliance Histor	y	
a) :	Status of ATR & any others		
	a dia au	Satisfactory (S)	
\	ading:	Satisfactory (S) Satisfactory but requires Improvement(SRI)	(gx
overall Gr			1
Overall Gr		Unsatisfactory (U)	- 60