FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: Katchar.				
Name of Road:		Repair of Road Gom Hanayampur chow	ek to	
Scheme/ Programme:		MAINTENANCE ·		
Package No. Road ID No. 2110570802				
Status of	the Project:	Onging/Completed/Under Maintenance		
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance		
Sl.No		Parameters to be Checked	Remarks	
1	Pavement	and the second of the second o		
a)	Road Junction Con	dition	۲	
b)	Condition of Surfacing		s 2 3	
c)	Riding Quality	ی		
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			
f)	ک Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slpoe & raincuts if any			
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting			
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			
c)	Condition of railings/slabs//approach for Bridges		NIA	
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			
4	Compliance History			
a)	Status of ATR & any others			
Overall G	Grading:	Satisfactory (S)	"2"	

Satisfactory (S)	"2"
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name:

SATISH CHAUDHARY

Degisnation At, Praypur

RDD, Manihari

(Signature)

Note: -> 21 49 PWD Road to Mallick for (Naraya for) kongly=10.5km)

To offin It 96 2018-19 Th FDR MR & 2018/1 514 24 08)