FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: Katikan.				
Name of Road:		efair of Road from Nano Garkhabur	yampur Charek to	
1.3.		MAINTENANCE		
			05708023	
Status of	the Project:	Onging/Completed/Under Maintenance		
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance		
SI.No		Parameters to be Checked	Remarks	
1	Pavement			
a)	Road Junction Con-	tion		
b)	Condition of Surfacing		ي ک	
c)	Riding Quality 5			
d)	Road Camber 5			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slpoe & raincuts if any			
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting		s painting \bowtie A	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			
c)	Condition of railings/slabs//approach for Bridges			
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			
4	Compliance History			
a)	Status of ATR & any others			
Overall Grading:		Satisfactory (S)	<u></u>	
		Satisfactory but requires Improveme	nt(SRI)	

Satisfactory (S)	2
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	,

SATISH CHAUDHARY Degisnation AE, Praypur

RWD Marihari

(Signature)

Note: > HE 44 PUD Road to mallickpur (Narayanpur) (Length = 10.5 km) यातु । प्राच कार्य में दी