


FIELD INSPECTION REPORT

Date of Inspection : -02/12/20		District: - Araria
Division : - R.W.D (W) Div. F.B. 4		Length (km): - 2.5 km
Name of the Road: - Dogachhi to Basgara Rampur		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition — ongoing	S/U
b)	Condition of Surfacing — "	S/U
c)	Riding Quality — "	S/U
d)	Road Camber — "	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. —	Yes/No
f)	Contraction Joints provided or not (CC Pavement) —	Yes/No
g)	Compaction of flank/slope & raincuts if any — ongoing	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts — ongoing	S/SRI/U
c)	Condition of railings/slab/approach for Bridges — "	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained — ongoing	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

(Signature)

 02/12/20
 SE