FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: Argusa					
Division: Roy Coxpersional			Length (km): 15.7 km		
Name of the Road: Kamalfur Dak Bunglow to Bousi Punis Bordy					
	Programme:	MAINTENANCE			
Package			Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Mnintenance New Connectivity/Up gradation/ Mnintenance			
Work is a case of:				Remarks	
Sl. No.	La Company		Property of the Control of the Contr		
, 1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance History				
a)	Status of ATR's	s & any others			

Overall Rating

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	1

Remark 1. under constrution PMGSY=II

(Signature)

NAME: Rauch Bilantal JE/Ranigami