FIELD INSPECTION REPORT

Date o	of Inspection:	64-12.2120	District:	epsol	
		Chopsa-I	Length (km): 4.19 1cm		
		Loss-Ghighter.	to Tolopy8(VP17)		
	e/Programme:	MAINTENANCE			
Package No.: Status of the Project: Ongoing/Comp		10 1 10 11	Road Id No.:		
			d/Under Maintenance	Not Storted	
	s a case of:	And the state of t	Up gradation/ Maintenanc	1	
Sl. No.		Parameters to	be checked	Re	emarks
1.	Pavement				
a)	Road Junction condition				S/Ų
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			exposed	es/No
f)	Contraction Joints provided or not (CC Pavement)			Y	es/No
g)	Compaction of flank/slope & raincuts if any			Y	es/No
2.	Cross Drainag	e	A STATE OF THE STA		
a)	Condition of head walls in Hume pipe culverts including its painting			ainting S/	SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/	SRI/U
c)	Condition of railings/slab/approach for Bridges			S/	SRI/U
3.	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				es/No
4.	Compliance His	story	erior sproude critical francia		
a) S	Status of ATR's	& any others			

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

N-12,2020

(Signature)

NAME:

DESIGNATION: