

FIELD INSPECTION REPORT

Date of Inspection : 5.12.2020	District: Saran (Chapra)
Division : Sonpur	Length (km): 1.10 K.M.
Name of the Road: Sabalpur 28 Dina Dr. Devenendra Singh Ke ghar se Bachha Rai Ke ghar Tak.	
Scheme/Programme: MAINTENANCE	M.R.
Package No.: M.R.N/19-20 Sonpur-20	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	M.R.
Work is a case of:	New Connectivity/Up gradation/ Maintenance M.R. New policy 2018.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Work Just started do to flood & rain.	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA.
g)	Compaction of flank/slope & raincuts if any	Yes/No NA.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI U NA.
c)	Condition of railings/slab/approach for Bridges	S/SRI U NA.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI.

(Signature)

J-2

NAME: Kanti Rgm.

DESIGNATION: J.E. Sonpur.