

FIELD INSPECTION REPORT

Date of Inspection :		District: SIWAN
Division : MAHARAJGANT		Length (km): 0.700 km
Name of the Road: BASANTPUR TO NAGAVLI VIA SIPAH		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/A
b)	Condition of Surfacing	S/A
c)	Riding Quality	S/A
d)	Road Camber	S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No PROVISION
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Mouitunjay Kv. Gari)
A.E

Manish Kumar Dha
04/12/20
A.E
(Signature)

NAME:

DESIGNATION:

Manish Kumar Dha
04/12/20
MANISH KUMAR DHA
(J.E)