

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District: Siwan
Division : Maharajganj		Length (km): 2.2 km
Name of the Road: Hilsar L024 to Nauwa.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance <i>ongoing</i>
Work is a case of:		New Connectivity/Up gradation/ Maintenance <i>upgrading</i>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>X</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>X</i>
4.	Compliance History	
a)	Status of ATR's & any others	— No —

Overall Rating :

Satisfactory (S)	<i>Satisfactory</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

S. E.
03/12/2020
(Ranbir Kumar)