FIELD INSPECTION REPORT

Date of Divisio	Inspection:	3/12/2020 District: - Si 2097	
Name o	of the Road: Programme:	Kismopyra to Madaspia	Μ
Packag	* 7	3054 New Mas 7 p. Road Id No.: Ongoing Completed Under Maintenance	20.2.3.6
Work is	s a case of:	New Connectivity/Ha and March	- Jan
Sl. No.		Parameters to be checked	Remarks
1.	Pavement		
a)	Road Junction condition		Set :
b)	Condition of Surfacing		8/U
c)	Riding Quality		1 87U
d)	Road Camber		28/1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
1)	Contraction Joints provided or not (CC Pavement)		N/Acs/No N/A Yes/No
3)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting &/SRI		N/S/SRI/U
h)	Condition of Abutment & Wing walls, Slab in RCC culverts		N/AS/SRI/U
c)	Condition of rai	ndition of railings/slab/approach for Bridges	
3.	Road Furniture NaS/SRI/U		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		The second secon
a)	Status of ATR's	& any others	No any

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature) A

NAME: Jibacky Pradod.