FIELD INSPECTION REPORT

					1		
Date of	Inspection: 6	14-12-20	District:	Sopi	algary		
Division	: KWDG		Length (kn		6-600		
Name of	the Road:	Harkhya to 1	Ramch	and arb	our Path		
Scheme/	Programme:	MAINTENANCE			,		
Package No.:			Road Id No		-4		
Status of the Project:		Ongoing/Completed/Under Maintenance					
Work is	a case of:	New Connectivity/Up	gradation/	Maintena	nce	100000000000000000000000000000000000000	
Sl. No.		Parameters to b	e checked			Remarks	-
1.	Pavement		ASA CAMARAS	9 4			
a)	Road Junction condition				S/U (S)	
b)	Condition of Surfacing				s/U (V		
c)	Riding Quality			9		S/U (V	1)
	-					S/U (S	7.
d)	Road Camber			- and		1.	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			, exposed	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)				Yes/No \	Jel	
g)	Compaction of flank/slope & raincuts if any			Yes/No -	fothedayon		
5/	F			And a contract	100000000000000000000000000000000000000	1.1.2.7.1	£.

a)	Collection of field white PCC only orts	S/SRI/U HA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	4 13
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No * P&
4.74	Compliance History	NA ATR
a)	Status of ATR's & any others	المالة على المالة

Condition of head walls in Hume pipe culverts including its painting

Overall Rating

a)

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Ajoy kum ero Tiwari

DESIGNATION: Executive Engineero

Cross Drainage

Scanned by CamScanner

(Signature)

S/SRI/U