


FIELD INSPECTION REPORT

Date of Inspection: 05/12/2020		District: Muzaffarpur
Division: Muzaffarpur West		Length (km): 3.33
Name of the Road: Bardkagaon to Motipur		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.: 31507408015	
Status of the Project:	Out of Maintenance	
Work is a case of:	New Connectivity/Up Gradation/Maintenance	
Sl. No.	Parameters to be Checked	Remarks
1.	Pavement	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slop & rain cuts if any	N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating : **Out of Maintenance**

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A


(Signature)

NAME: KISHORE KUMAR
DESIGNATION: EXECUTIVE ENGINEER