


## FIELD INSPECTION REPORT

|                                                           |                                                                                                                      |                              |
|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|------------------------------|
| <b>Date of Inspection: 05/12/2020</b>                     |                                                                                                                      | <b>District: Muzaffarpur</b> |
| <b>Division: Muzaffarpur West</b>                         |                                                                                                                      | <b>Length (km):1.34</b>      |
| <b>Name of the Road: Sarmaspur to Chintaman-pur Dhala</b> |                                                                                                                      |                              |
| <b>Scheme/Programme:</b>                                  | MAINTENANCE                                                                                                          |                              |
| <b>Package No.:</b>                                       | Road Id No.:31507408020                                                                                              |                              |
| <b>Status of the Project:</b>                             | Out of Maintenance                                                                                                   |                              |
| <b>Work is a case of:</b>                                 | New Connectivity/Up Gradation/Maintenance                                                                            |                              |
| <b>Sl. No.</b>                                            | <b>Parameters to be Checked</b>                                                                                      | <b>Remarks</b>               |
| <b>1.</b>                                                 | <b>Pavement</b>                                                                                                      |                              |
| a)                                                        | Road Junction Condition                                                                                              | N/A                          |
| b)                                                        | Condition of Surfacing                                                                                               | N/A                          |
| c)                                                        | Riding Quality                                                                                                       | N/A                          |
| d)                                                        | Road Camber                                                                                                          | N/A                          |
| e)                                                        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | N/A                          |
| f)                                                        | Contraction Joints provided or not (CC Pavement)                                                                     | N/A                          |
| g)                                                        | Compaction of flank/slop & rain cuts if any                                                                          | N/A                          |
| <b>2.</b>                                                 | <b>Cross Drainage</b>                                                                                                |                              |
| a)                                                        | Condition of head walls in Hume pipe culverts including its painting                                                 | N/A                          |
| b)                                                        | Condition of Abutment & Wing Walls, Slab in RCC Culverts                                                             | N/A                          |
| c)                                                        | Condition of railings/slab/approach for Bridges                                                                      | N/A                          |
| <b>3.</b>                                                 | <b>Road Furniture</b>                                                                                                |                              |
| a)                                                        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | N/A                          |
| <b>4.</b>                                                 | <b>Compliance History</b>                                                                                            |                              |
| a)                                                        | Status of ATR's & any others                                                                                         | NO                           |

Overall Rating : **Out of Maintenance**

|                                                    |     |
|----------------------------------------------------|-----|
| <b>Satisfactory (S)</b>                            | N/A |
| <b>Satisfactory but requires Improvement (SRI)</b> | N/A |
| <b>Unsatisfactory (U)</b>                          | N/A |

  
(Signature)

**NAME: KISHORE KUMAR**  
**DESIGNATION: EXECUTIVE ENGINEER**