

FIELD INSPECTION REPORT

Date of Inspection :	5/12/2020	District:	VAISHALI
Division :	MAHAR	Length (km):	900
Name of the Road:	N.H-103 Andharawar to Dhadhaha chowk		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Mahar	Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
---------	--------------------------	---------

1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	sub grading of 5th & 6th lane
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/U NA
c)	Condition of railings/slab/approach for Bridges	S/S/U NA

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	only for sign board

4.	Compliance History	work has been started
a)	Status of ATR's & any others	

Overall Rating : *At 1st pothole, camber of 5th & 6th lane*

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

5/12/20
(Signature)

NAME: *Uday Shanker pr Singh*