

FIELD INSPECTION REPORT

Date of Inspection :	4.12.20	District:	Vaishali
Division :	Mahua	Length (km):	2.014
Name of the Road:	Hakimpur to Jalalpur village		
Scheme/Programme:	MAINTENANCE	Idone not started	
Package No.:	08	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Agreement Done
Work not started.

NAME:

DESIGNATION: कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, महुआ

(Signature)