FIELD INSPECTION REPORT

Date of	Inspection :	5/12/20 District: Valabili	
Divisio	n: Haziful	Length (km): 3 30 Km	
Name o	f the Road: D	Burnages bojasa to Vainhali Prakted Kachari Tak	
Scheme/Programme: MAINTENANCE Mg			
Package	100000000000000000000000000000000000000	Road Id No.:	
	f the Project:	Ongoing Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance	
SI. No.			Remarks
1.	Pavement		
a	Road Junction condition		S/U
b):	Condition of Surfacing		S/U
()	Riding Quality		(5/0)
d):	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
n	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No)
2	Gross Drainage		1. 6
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRL/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
1.	Road Purvitu	re	
(a) S	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained		
	Compliance History		THE T
) S	tatus of ATR's	& any others work in Progress	
rall Rat	ting :	Entletistant (5)	3
		Satisfactory (S) Satisfactory but requires Improvement (SRI)	
		Battatactory but requires improvement (Star)	

Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION: