

# FIELD INSPECTION REPORT

Date of Inspection :	5-12-20	District:	Vaishali
Division :	Mahua	Length (km):	
Name of the Road:	Mahua Munetarpan PWD road near Bakshou chowk H.S		
Scheme/Programme:	MAINTENANCE		
Package No.:	6/1A-20	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Agreement not done.  
Bader  
5-12-20  
J.E

5-12-20  
(Signature)

NAME:

DESIGNATION: