

FIELD INSPECTION REPORT

Date of Inspection :	05.12.2020	District:	Vaidhali
Division :	Mechanics	Length (km):	2.40 km
Name of the Road:	Deva Chowk R.E.O. Road to Maheshwar via panapur, K		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/15-20/Mechanics/05	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (Work not started)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	H.A. S/U
b)	Condition of Surfacing	H.A. S/U
c)	Riding Quality	H.A. S/U
d)	Road Camber	H.A. S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H.A. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H.A. Yes/No
g)	Compaction of flank/slope & raincuts if any	H.A. Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	H.A. S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	H.A. S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H.A. S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	H.A. Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 05-012-2020

NAME: SHRABAN KUMAR PRASAD

DESIGNATION: A.E.R.W.D.

FIELD INSPECTION REPORT

Date of Inspection:	05-12-2020	District:	Vaidhali
Division:	Madhwa	Length (km):	1.20 km
Name of the Road:	Market Warpur - Adipurigala Pokar		
Scheme Programme:	MAINTENANCE		
Package No.:	01/R-H/19-20/Madhw/01	Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance <i>(Work not started)</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A. S/U
b)	Condition of Surfacing	H.A. S/U
c)	Riding Quality	H.A. S/U
d)	Road Camber	H.A. S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H.A. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H.A. Yes/No
g)	Compaction of flank/slope & raincuts if any	H.A. Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A. S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	H.A. S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H.A. S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	H.A. Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 05.12.2020

NAME: SHRABAN KUMAR PRASAD
DESIGNATION: A.E.R.W.D.