FIELD INSPECTION REPORT

		FIELD INSPEC	HUN KEPUKI		
Date of	Inspection:	7-12-20	District: Valshow		l
Division: Malvery. Name of the Road: Puccikers of road from Herik of word Scheme/Programme: MAINTENANCE MAINTENANCE			Length (km): 4 · 2 0/2 ~	11.110	numt'
Name o	of the Road: Pu	elikowa of me	d from Herry of word	2 a had but	I w w
Scheme	Programme:	MAINTENANCE	h.22 ha		1
Packag	e No .: + 110	4-20	Road Id No.:		1
	of the Project:	Ongoing/Completed/U	Under Maintenance		1
Work is a case of: New Connectivity/U		New Connectivity/Up	p gradation/ Maintenance Remai		(S
Sl. No.	Parameters to be checked			1	
1.	Pavement	4			
a)	Road Junction condition			S/U	≯
					Ĭ.
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber				7/
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	\dashv
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	N.A
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	ge	tions of the state of	W. Hardest - 48	
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	\
c)	Condition of ra	Condition of railings/slab/approach for Bridges			_
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance H	istory			
a)	Status of ATR'	s & any others			
					-

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Agreement rust doine.

(Signature)

NAME:

DESIGNATION: