## FIELD INSPECTION

Data	of	FIELD INSPEC	CTION REPORT			
Eate of Inspection: 05 0 2 22						
1.0100			V		, bes	
Name of the Road: Parchyset chowk Scheme/Programme: MAINTENANCE			Abukarur tobalde revi house to pirmuhe			
Packa	age No.: 22	MAINTENANCE		MO RUK		
Status	s of the Project:	Ongoing/Completed/	Road Id No.:			
Work	Work is a case of: New Connectivity/		p gradation/ Maintenance			
SI. No	D.	Parameters to be checked		Remarks		
1.	Pavement					
a)	Road Junction condition		the statement in the same	S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			S/U		
d)	Road Camber		S/U			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No	Ala	
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
c)	Condition of railings/slab/approach for Bridges		S/SRI/U			
3.	Road Furniture			3/314/0		
a) s	Whether sign bo stones/Pavement re	pards/informatory/cautio oad markings are provi	Yes/No			
1. (	Compliance History					
) S	tatus of ATR's & any others			the the same and		
					/	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

work not started

(Signature)

NAME:

DESIGNATION:

ग्रामीण कार्य विभाग कार्य प्रमंडल, महुआ

Scanned with CamScanner