

FIELD INSPECTOR'S REPORT

Date of Inspection: 6/12/2020

District: SITAMARHI

Division: SITAMARHI

Length (km): 2.320 KM

Name of the Road: ~~ANON DHORRA~~ - ANHADI MATH

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work not started


Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A SAT
b)	Condition of Surfacing	N/A SAT
c)	Riding Quality	N/A SAT
d)	Road Camber	N/A SAT
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	} N/A.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started


(Signature)

NAME: Lalit Mohan Kumar

DESIGNATION: J.E. Riga