

FIELD INSPECTION REPORT

Date of Inspection: 6/12/2020 District: SITAPURHI
 Division: SITAPURHI Length (km): 3.277 Km
 Name of the Road: PAKARI TO PAKAR
 Scheme/Programme: MAINTENANCE
 Package No. Road Id No.

Status of the Project: ☒ Ongoing/Completed/Under Maintenance *Work not started*
 Work is a case of: ☐ New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	} H/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started.

6/12/20
 (Signature)

NAME: Lalit Mohan Ram.

DESIGNATION: JE Riga.