FIELD INSPECTION REPORT

Date of Inspection: 5.12.20 District:- Sheohar.					
Division:-RWD, Works Div. Sheohar Length (km):- 3.8					
		atch pur to Pc	Busuabait Lehinto	8000	
	/Programme:-	MAINTENA	NCE		
Package			Road Id No.:		
Status o	e				
	Work is a case of: New Connectivity/Up gradation/ Mainte				
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			· S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks,			Yes/No	
1	exposed aggregates in case of CC Pavement				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag				
a)	Condition of head walls in Hume pipe culverts S/SRL				
₹	including its painting			3000 000 000 000	
b)	Condition of Abutments & Wing walls, Slab in RCC			S/SRI/U	
	culverts				
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furniture			2	
a)	Whether sing board/informatory/cautionary Board/			Yes/No	
	Km & 200m stones/Pavement road marking are				
	provided and maintained				
4.	Compliance History				
a)		's & any others			
		The second secon		1 1	

WOOK is under tender disposal

(Signature)

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Ratesh Kumar

DESIGNATION: Juniour engineer