

Under Maintenance policy
December 2018

FIELD INSPECTION REPORT

Block - Piprahi

Date of Inspection : - 4.12.2020	District: - Sheohar
Division : - Sheohar	Length (km): - 2.530 KM
Name of the Road: - Kamrauli to Harkarba	
Scheme/Programme: MAINTENANCE	
Package No.: - BR-32R-004	Road Id No.: - 84072
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	Tender process

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Work is under Tender process. so there is no any remarks.
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Kumar
4.12.2020
(Signature)

NAME: - Sudhir Kumar
DESIGNATION: - A.E.