

Under Maintenance Policy
December 2018

FIELD INSPECTION REPORT

Block - piprahi

Date of Inspection :	- 4.12.2020	District: -	Sheohar
Division : -	Sheohar	Length (km): -	1.450 km.
Name of the Road: -	Dhankaul to Minapur		
Scheme/Programme:	MAINTENANCE ✓		
Package No.: -	BR-032-02	Road Id No.: -	86975
Status of the Project:	Ongoing/Completed/Under Maintenance	Not started ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	Work has been not started. so there is no remarks	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sudhir Kumar
4.12.2020
(Signature)

NAME: - Sudhir Kumar
DESIGNATION: - A. Engineer