Date of Inspection: 05-12- 2020 District: East Char				mbeison
Division: RND Chakla Length (Km): 1.050				
, A 1 .11 .				
Bood ID No. 2 17 0 22 DA011-				
Fackage No.				
Status of the Project : Ongoing/Completed/Under Maintenance Work is a case of : New Connectivity/Up Gradation/ Maintenance				
	case of :	Remarks		
SI. No.	Parameters to be checked			
1,	Pavement			
a)	Road Junction condition			-NA-
b)	Condition of Surfacing			- NA-
c)	Riding Quality			- NA-
d)	Road Camber			- NA -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			- NA -
f)	Contraction Joints provided or not (CC Pavement)			-
g)	Compaction of flank/slope & raincuts if any			_
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting - NA-			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			
c)	Condition of railings/slab/approach for Bridges			<u> </u>
3,	Road Furniture			
aj	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			- NA-
4,	Compliance History		Т	
a)	Status of ATR's & any	y others		
	Overall Rating :	Satisfactory (S) Satisfactory but requires	s improvement (SRI)	Ongoing
	Remarks!-	Unsatisfactory (U)	Pot pater work	in brogses.
	MANE		∀ (Signatu)	re)

NAME:

DESIGNATION: