

# FIELD INSPECTION REPORT

|                                         |                                                                                                                     |                                            |  |
|-----------------------------------------|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------|--|
| Date of Inspection : 05-12-2020         |                                                                                                                     | District : East Champaran                  |  |
| Division : RWD Chalcia                  |                                                                                                                     | Length (Km): 5.906                         |  |
| Name of the Road : RFO Road to Sasarpur |                                                                                                                     |                                            |  |
| Scheme/Programme :                      |                                                                                                                     | MAINTENANCE                                |  |
| Package No.: MR-N/15-20 Chalcia/15      |                                                                                                                     | Road ID No.: 31708202041                   |  |
| Status of the Project :                 |                                                                                                                     | Ongoing/Completed/Under Maintenance        |  |
| Work is a case of :                     |                                                                                                                     | New Connectivity/Up Gradation/ Maintenance |  |
| Sl. No.                                 | Parameters to be checked                                                                                            | Remarks                                    |  |
| 1,                                      | Pavement                                                                                                            |                                            |  |
| a)                                      | Road Junction condition                                                                                             | - On going -                               |  |
| b)                                      | Condition of Surfacing                                                                                              | -                                          |  |
| c)                                      | Riding Quality                                                                                                      | -                                          |  |
| d)                                      | Road Camber                                                                                                         | -                                          |  |
| e)                                      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                        | -                                          |  |
| f)                                      | Contraction Joints provided or not (CC Pavement)                                                                    | -                                          |  |
| g)                                      | Compaction of flank/slope & raincuts if any                                                                         | -                                          |  |
| 2,                                      | Cross Drainage                                                                                                      |                                            |  |
| a)                                      | Condition of head walls in Hume pipe culverts including its painting                                                | -                                          |  |
| b)                                      | Condition of Abutment & Wing walls, Slab in RCC Culverts                                                            | -                                          |  |
| c)                                      | Condition of railings/slab/approach for Bridges                                                                     | -                                          |  |
| 3,                                      | Road Furniture                                                                                                      |                                            |  |
| a)                                      | Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained | -                                          |  |
| 4,                                      | Compliance History                                                                                                  |                                            |  |
| a)                                      | Status of ATR's & any others                                                                                        |                                            |  |

|                  |                                             |  |
|------------------|---------------------------------------------|--|
| Overall Rating : | Satisfactory (S)                            |  |
|                  | Satisfactory but requires improvement (SRI) |  |
|                  | Unsatisfactory (U)                          |  |

Remarks - Work started.

*[Signature]*  
5/12/20  
(Signature)

NAME :

DESIGNATION :

*[Signature]*  
5-12-2020