

FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020		District : East Champaran	
Division : RWD Chalcia		Length (Km): 10.00 km	
Name of the Road : Rampur Keras to Basia Dekaha			
Scheme/Programme :		MAINTENANCE (New)	
Package No.: MR-N/19-20 Chalcia/04		Road ID No.: 31708202043	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- NA -	
f)	Contraction Joints provided or not (CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	-	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	- NA -	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- NA -	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Remarks:- Work in progress.


 (Signature)
 5/12/20

NAME :

DESIGNATION :


 5.12.2020
 J.E