FIELD INSPECTION REPORT

Date of Inspection: 04-12-2020 District: E. Champarn				
Division: Chakia Length (Km):				
Name of	the Road : Burdok	an kaluantur RE		254.50 44 4
Name of the Road: Birdaban kalyanpur RED Road To Badharu Scheme/Programme: MAINTENANCE (NOW)				war mananand
Package		IMAINTENANCE (IVE		20.00
	the Project :	Road ID No.: 31708202068		202068
		Ongoing/Completed/Under Maintenance		
	a case of : New Connectivity/Up Gradation/ Maintenance			
SI. No.				Remarks
September 1	Pavement			
a)	Road Junction condition			<u>'s'</u>
b)	Condition of Surfacing			Is!
c)	Riding Quality			15'
d)	Road Camber			18'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			in _
1)	Contraction Joints provided or not (CC Pavement)			-
g)	Compaction of flank/slope & raincuts if any			\'S'
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			<u>'s'</u>
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			's'
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			's'
4,	Compliance History			
a)	Status of ATR's & an	y others		·
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	Overall Rating :	Satisfactory (S) Satisfactory but require:	s Improvement (SRI)	

Same points in this Road sequenced Flank but land are not available for plank fail Filling.

(Signature)

NAME:

DESIGNATION: